


INNOVA-Teco


**Correct and complete way to
treat a kiln**



Kiln preparation







Primer

Essential for cleaning and opening the pore





Material preparation





Application of revestment

































**Application of R-10000 revestment
on platelets**









**Treatment of suspended exterior kiln roof
of cordierite with P-60000.**

dfd

Reduction of temperature up to 50%











**Treatment of brick roof with P-60000
50% temperature reduction**







